

## Product and Technical News in Nov. 2017

### XPOSE

V1.2.1.78

- **Optimization**

#### 1.For VENUS X3/VENUS X7

1)The layout of EDID setting.

It would work in VENUS X3 for software version V1.83, and VENUS X7 for software version V1.41.

2)EDID files is updated.

3)4K30Hz input module setting operation.

①4K2K mode:

steps: select input module->select working mode->Height->EDID parameter

②4K1K mode:

steps: select input module->select working mode->input type->EDID parameter

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

### C480

V0.87

- **Update**

1)Test Pattern is added

2)Hot backup is added

3)3D mode is added under Split Mode

4)LOGO Capture is added

5)Freeze for LOGO Capture is added

6)Delay recall function is added.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen,Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: [support@rgblink.com](mailto:support@rgblink.com) <http://www.rgblink.com>

1 / 4

7)The sign for 4K mode selection and reboot is added

8)Vertical Mapping Mode cannot support multi Input.

- **Optimization**

1)EDID of DVI2K and HDMI2K

2)Remove more than 1920x1080 resolution,so The maximum output resolution is 1920x1080.

3)Fluency of TAKE under Preview Mode

- **Problem Solved**

1)Screen tearing when output format below 30Hz.

- **Download link for latest software**

**Download Link:**

Chinese site: [http://www.rgblink.com/products\\_detail.aspx?id=753](http://www.rgblink.com/products_detail.aspx?id=753)

English site: [http://www.rgblink.com/en/products\\_detail.aspx?id=754](http://www.rgblink.com/en/products_detail.aspx?id=754)

Contact sales or customer support personnel of RGBlink to get the latest software.

## **MSP 200PRO**

V1.61

- **Optimization**

1)The output format would be recognized as 1080P automatically, when the input source is TP.

2)The switching between HDMI and USB signal is optimized. The probability of blank screen during the signals switching is reduced.

3)The latest software greatly reduces the probability of device turns to stuck when it's working.

- **Problem Solved**

1) Few flash points might flash on boot screen.

2)Few flash points might flash on 200PRO's monitor is fixed.

3)Few flash points might display in DVI output is fixed.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen,Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: [support@rgblink.com](mailto:support@rgblink.com) <http://www.rgblink.com>

- **Download link for latest software**

**Download Link:**

Chinese site: [http://www.rgblink.com/products\\_detail.aspx?id=714](http://www.rgblink.com/products_detail.aspx?id=714)

English site: [http://www.rgblink.com/en/products\\_detail.aspx?id=715](http://www.rgblink.com/en/products_detail.aspx?id=715)

Contact sales or customer support personnel of RGBlink to get the latest software.

**T-ONE****Keyboard V1.02**

- **Update**

1)The amount of Chinese character up to 30 that show on LED screen

2)It would work under software version V1.0.0.2

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

**Software V1.0.0.22**

- **Update**

1)Extended screen display is added: under operation mode, PST pictures only display on the touch screen, and the PGM pictures display on extended screen.

2)The display of keyboard version, virtual keyboard switch and extended display setting is added.

3)The layout of input/output setting, device IP parameter and boot time setting are all can be written by front panel keyboard.

- **Optimization**

1)T-ONE IP setting: Set T-ONE IP on XONE, do not need back to desktop to set device IP.

2)LOGO setting and return value of LOGO setting.

3)It would be switch to operation interface when PRESET button is pressed.

4)Operation interface: PGM in bottom left, functions of quick split, LOGO, scale and crop are all in third level menu.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen,Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: [support@rgblink.com](mailto:support@rgblink.com) <http://www.rgblink.com>

5)Preview of bank: setting menu that on top left is canceled, the location of setting menu is changed to third menu.

- **Problem Solved**

1)The irregular display of color bar from test pattern.

2)The switching time of fade turn to 0 when the switching method change. Such as, it changes to T-BAR from TAEK/CUT. And please pay attentions to the follows:

A. T-ONE software version V1.02 would work with XONE software version V1.0.0.2.

B. T-ONE software version V0.10 would work with XOINE software version V1.0.0.20 or lower version.

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.