



Product and Technical News in Sept. 2018

M2

Version: V2.01

- **Optimization**

1. Solved PVW system lagging issue.

- **Download link for latest software**

(EN) https://rgblink.com/UploadFile/ePic/M2_Firmware_EN_V2.01_20180911.zip

[p](#)

(CN) https://www.rgblink.cn/UploadFile/ePic/M2_

Contact sales or customer support personnel of RGBlink to get the latest software.

M3

Version: V1.83

- **Problem Solved**

1. The latest software of D-HDMI and D-SDI input modules is compatible.

- **Download link for latest software**

(EN) https://rgblink.com/UploadFile/ePic/M3_Firmware_EN_V1.83_20180911.zip

[p](#)

(CN) <https://www.rgblink.cn/UploadFile/ePic/M3>

Contact sales or customer support personnel of RGBlink to get the latest software.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen, Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: support@rgblink.com <http://www.rgblink.com>

1 / 4



XTOOL

Version: V1.0.0.32

- **Optimization**

- 1. The function of X1 firmware name identification is removed.**
- 2. The Device Type and Series No. of V2S and D6 are available to show on XTOOL.**

- **Download link for latest software**

(EN) <https://rgblink.com/software> <https://rgblink.com/xtools-windows>

(CN) https://rgblink.cn/xtools-windows_

Contact sales or customer support personnel of RGBlink to get the latest software.

VENUS X2

Version: V2.53

- **Optimization**

- 1. The SDI output module is available.**

(For the newest features of VENUS X2, the software version of XPOSE should be V1.2.5.0 or higher.)

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

VENUS X3

Version: V2.33

- **Optimization**

- 1. The 4K@60 input module is optimized.**

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen, Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: support@rgblink.com <http://www.rgblink.com>



- **Update**

- 1. The Property Setting is available for D-HDMI and D-SDI input modules.**

- **Problem Solved**

- 1. Controlled via T-ONE, it's not smooth for T-Bar switching.**

(For the newest features of VENUS X3, the software version of XPOSE should be V1.2.6.0 or higher.)

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

VENUS X7

Version: V2.50

- **Optimization**

- 1. The 4K@60 input module is optimized.**

- **Update**

- 1. The Property Setting is available for D-HDMI and D-SDI input modules.**

- 2. Multi H264 output modules can be used simultaneously.**

- **Problem Solved**

- 1. Controlled via T-ONE, it's not smooth for T-Bar switching.**

- 2. When the function of Source Merge is available and the device reboots, it would be failure to save the data.**

(For the newest features of VENUS X7, the software version of XPOSE should be V1.2.6.0 or higher.)

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen,Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: support@rgblink.com <http://www.rgblink.com>



XPOSE

Version: V1.2.6.0

- **Update**

- (1) For VENUS X2**

- A. The 4K signal is available for Custom Preview Mode.

- (2) For VENUS X3**

- A. The Property Setting is available for D-HDMI and D-SDI input modules.

- (2) For VENUS X7**

- A. The Property Setting is available for D-HDMI and D-SDI input modules.

- **Problem Solved**

- (1) For VENUS X2**

- A. Under Matrix Mode, the interface would display abnormally.

- B. When the device is power on, the 4K signal source would display abnormally.

- (2) For VENUS X7**

- A. Under Videowall Mode, if the Auto Take switch is off, then the Banks cannot be saved.

- B. Under Preview Mode, the Container Parameters setting issue is solved.

- C. The layout would disorder when the script is loaded.

Please pay attention to the follow:

As the latest XPOSE is used (software version is V1.2.6.0), the software version for the devices is required:

1) V1.09 for VENUS X1pro e

2) V2.50 or higher for VENUS X2

3) V2.33 for VENUS X3

4) V2.50 for VENUS X7

5) V1.87 or higher for D6

- **Download link for latest software**

Contact sales or customer support personnel of RGBlink to get the latest software.

Address: S601 Weiye Building Torch Hi-Tech Industrial Development Zone Xiamen,Fujian P.R.C

Tel: 4008 592 315

Fax: +86 592 5788216

Email: support@rgblink.com <http://www.rgblink.com>